

Tourer Damp Report



Customer Name: **Walter Clark**
Address: **38 Rockwood Drive,**
Town/City: **SKIPTON**
Postcode: **BD23 1UW**
Vehicle Make and Model: **STERLING EUROPA 460**
CRIS/VIN Number: **SGDS006 SW60828782**
Job Reference: **-NVdj-P5k2tL_FuGhNeO**

Guidance Notes

X - unable to check area due to obstruction or vehicle construction

Moisture levels between 0-15% - no cause for concern, only readings of over 15% are recorded.

Moisture levels between 15-20% - may require further investigation. Compare with average readings and consider a recheck after 3 months.

Moisture levels between 20-30% - will require further investigations to look for other possible indications of water ingress. Possible resealing required to avoid further degrading.

Moisture levels 30% and above - may indicate that structural damage or deterioration is occurring. Possible resealing required to avoid further degrading followed by immediate rectification action, as necessary.

Comments and Recommendations

High damp readings front window
High damp readings rear window and offside rear

Damp meter calibration check figure: 17%
Weather Conditions: Sunny
Ambient Temperature: 16
Damp meter make and model: Protimeter Survey Master
Service Technician Name: Kale

Signed by Kale on behalf of Caravan Dan Ltd

Date: Wed, 17 May 2023



Tourer Damp Report

